

Product/Process Change Notification PCN # 090216-F213

Product:	FFC 1.00 mm Pitch ; Vertical Mount ; Surface Mount Connectors		Part Numbers Affected:	F213-XX21-10x-Z
Issue Date:	Sept 1,2016			
Page(s):	1/1			
Distribution:	Active and Contract Customers			

Subject: Discontinuance of Product - Insulator Mold Tooling is badly worn and cannot product quality parts .

<p>Discontinued Parts: F213-xx21-10x-Z Where XX is Circuit Number (Size) and X is packaging</p>	<p>Replacement Parts: F213-XX28-10X-Z</p>
---	---

1. Post Sept 2016 parts have solder pad on bottom intended to increase stability on PCB.
2. Pin #1 identifier is not molded into part; Non - symmetry of part only allows attachment to PCB in one orientation only.

Product Line Implementation Date: All orders shipped after Sept 2, 2016; There will be no last order date due to the above reason; SMP reserves the right to terminate production at any time at its own discretion. SMP will make every effort to meet customer order requirements

Last Order Entry Date : N/A

Product Specification: No change to product specification.

For questions regarding this PCN contact:

SMP Technology Inc
Product Manager
Tel : 831-438-9191
Email : sales@smp-tech.com